

LEARJET

55/60 Series WINDSHIELD & WINDOW SERVICES



Windshields

Part Number

6600394-1 (LH - S/N: 1-235)
6600394-2 (RH - S/N: 1-235)
6600394-003 (LH - S/N: 236 & ON)
6600394-004 (RH - S/N: 236 & ON)

Cabin Windows

Part Number

LA6600405-30 (Aft RH)*
LA6600405-31 (Aft LH)*
LA6600405-32 (Common)*
LA6600405-830 (Aft RH - Undrilled)
LA6600405-831 (Aft LH - Undrilled)
LA6600405-832 (Undrilled)

* Includes Installation Instructions and Hardware.

Aerostructures • Composite Manufacturing • Transparencies • Installation & Repairs

FAA / PMA Approved
Available for Immediate Delivery
High Quality-Low Cost

 **LEE**
AEROSPACE
THE VISIBLE DIFFERENCE

Part Numbers for Reference Only

FAA/CRS #YLIR863L

9323 East 34th Street North, Wichita, KS 67226 • 1-800-379-6840 • 316-636-9200
Fax: 316-636-9256 • Sales@leeaerospace.com • www.LeeAerospace.com

FAA/EASA REPAIR STATION

SERVICES

As the industry leader in transparencies, Lee Aerospace has been operating a full service manufacturing and repair facility since 1989. Our team of Certified Window repairmen can inspect every window in your aircraft and provide you with an expert, detailed evaluation on the condition of your aircraft windows.

As the OEM for some of the largest aircraft manufacturers in the world, Lee Aerospace qualified team of FAA certified technicians can provide you with a detailed inspection, quick repair turn around, or accurately installed windshields and windows.

24-Hour AOG Service 1-800-379-6840

Pre-Buy Inspection Repair Installation

FAA Certified Repair Station #YLIR863L
EASA Approved Repair Station #145.4630
FAA Certified Drug/Alcohol Program
Hangarkeepers Insurance

